

symbol[®] LS 9100

Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner please contact an Edmunds hardware technician.



1




Set Synapse PC Wedge Defaults

2



Enable LS 9100 Communication

3



SCAN OPTIONS

4



Send Control Key Codes

5



<DATA> <SUFFIX>

6



ENTER