


symbol[®] LS 9208

Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner please contact an Edmunds hardware technician.



Keyboard Wedge Interface



1



IBM PC/AT & IBM PC Compatibles¹

2



Enable

3



Scan Options

4



<DATA> <SUFFIX>

5



Enter